

BUILDING SAFETY CERTIFICATE

Certified that the existing building Vibgyor Rise School at Sr no 12, Hissa no 1 to 5, City survey No 594, 595 and 597, Pimple Saudagar, Taluka Haveli, Pune 411027. is having block (s) / Floor(s) as per details below.

Detail Block(s) in School	Block (1)
No. of Floor(s) in the Block	Ground Floor + 6 Floor.

The building is owned/occupied by Vibgyor Rise School run by Global Education Foundation at Sr no 12, Hissa no 1 to 5, City survey No 594, 595 and 597, Pimple Saudagar, Taluka Haveli, Pune 411027. have complied with the Building safety requirements and verified by the officers concerned of Public Works Department Pune on 26/05/2025 in the presence of, Mrs. Meenakshi Mestry, Principal, Vibgyor Rise School at Sr no 12, Hissa no 1 to 5, City survey No 594, 595 and 597, Pimple Saudagar, Taluka Haveli, Pune 411027, and that the building is fit for occupancy for running school with effect from 26/05/2025 for a period of One year

Issued on 30/05/2025 at Pune by


(S.A. Kotkar)

Sub Divisional Engineer,
P. W. Sub Division No.5
Pune-411011.




OW.No./ DB / NOC / 4156 /2025
Office of the Executive Engineer,
Pune Public Works Division, Pune-01.

Date :-

30 MAY 2025

'Countersigned'


(Dr. S.R. Katkar)


Executive Engineer,
Pune Public Works Division,
Pune-411001.

Copy to :- 1 Vibgyor Rise School at Sr no 12, Hissa no 1 to 5, City survey No 594, 595 and 597, Pimple Saudagar, Taluka Haveli, Pune 411027.

2. Sub Divisional Engineer, P. W. Sub Division No.5, Pune 411001.


Admin Manager
Vibgyor Rise Pimple Saudagar




Principal
Vibgyor Rise Pimple Saudagar